FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

GROOVE WALL FACE IS LARGELY INCLINED (1.5°)

FIG. 10




FIG. 11




FIG. 12

